


## ELECTRONIC OVER LOAD RELAY (EOLR)



- Motor Currents are measured through current Transformers and processed through high accurate digital Method. So overload tripping is accurate and early.
- Motor overload currents can be set through seven segment display with keypad.